


SendIt Rev C Connectors

<https://github.com/hoeken/sendit>



Optional External Power Connector:
Screw Terminal 3.5mm

- 1: +12-30v
- 2: Ground

Analog Inputs Connector:
Screw Terminal 3.5mm

- 1: +VOLTAGE
- 2: Signal
- 3: Ground

Voltage Select Options

1. 3.3v
2. 5.0v
3. 24v
4. External Power

Measurement Select Options

1. 4-20ma sensor
2. 0-32v voltage measurement
3. Raw ADC Input (max 3.3v)
4. 10k pullup (switch to gnd)
5. 0-5v voltage measurement

Notes

You **must** install a jumper on both top and bottom settings for measurement select. The top and bottom setting must be the same.